




With no internal coils:



A possibility with one internal coil:



Note 1: For GE, coil is 

Note 2: For Siemens, right power rail is missing.