



Step 4. Stamp part.




Step 5 Move stamp up, retentive timer.




Step 6. Push to conveyor.




Step 7. Retract PCYL2.




Step 8. Move out.




10



11





(End)