



Note: optional "and Run" in transitions not in CL solution. Probably better to transition out of Step-1 regardless of "Run" because when "Run" is turned off, many conveyors "coast" for a little.